


b≤125	18	22	26	30	34	38	42	46	54
b>125	24	28	32	36	40	44	48	52	60
s	10	13	17	19	22	24	27	30	36
k min.	3,85	5,15	6,22	7,32	8,62	9,82	11,28	12,28	14,78
e	11,05	14,38	18,90	21,10	24,49	26,75	30,14	33,53	39,98
	10	13	17	19	22	24	27	30	36
<b>Diameter</b>	<b>M6</b>	<b>M8</b>	<b>M10</b>	<b>M12</b>	<b>M14</b>	<b>M16</b>	<b>M18</b>	<b>M20</b>	<b>M24</b>
40	● ●	● ●	● ●	● ●					
45	● ●	● ●	● ●	● ●					
50	● ●	● ●	● ●	● ●	● ●	● ●			
55	● ●	● ●	● ●	● ●	● ●	● ●			
60	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	
65	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	
70	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	
75	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	
80	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
90	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
100	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
110	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
120	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
130	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
140	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
150	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
160		● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
170		● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
180		● ●	● ●	● ●	● ●	● ●	● ●	● ●	● ●
190									● ●
200									● ●
<b>Box/Piece</b>	200 ≥45 100	200 ≥45 100 ≥80 50 ≥180 25	100 ≥50 50 ≥160 25 ≥210 10	50 ≥100 25 ≥160 10	50 ≥100 25 ≥150 10	25 ≥150 10	25 ≥130 10	25 ≥130 10	10 ≥160 5

