



k max.	2,8	3,5	4,0	5,3	6,4	7,5	8,8	10,0	11,5	12,5	14,0	15,0	17,0	18,7
s	7	8	10	13	17	19	22	24	27	30	32	36	41	46
e	7,66	8,79	11,05	14,38	18,90	21,10	24,49	26,75	30,14	33,53	35,72	39,98	45,20	50,85
Hex	7	8	10	13	17	19	22	24	27	30	32	36	41	46
Diameter	M4	M5	M6	M8	M10	M12	M14	M16	M18	M20	M22	M24	M27	M30
5														
6														
8	●	●	●	●										
10	●	●	●	●	●	●								
12	●	●	●	●	●	●	●							
16	●	●	●	●	●	●	●	●						
20	●	●	●	●	●	●	●	●	●					
25	●	●	●	●	●	●	●	●	●	●				
30	●	●	●	●	●	●	●	●	●	●	●			
35	●	●	●	●	●	●	●	●	●	●	●	●		
40	●	●	●	●	●	●	●	●	●	●	●	●	●	
45	●	●	●	●	●	●	●	●	●	●	●	●	●	●
50	●	●	●	●	●	●	●	●	●	●	●	●	●	●
55	●	●	●	●	●	●	●	●	●	●	●	●	●	●
60	●	●	●	●	●	●	●	●	●	●	●	●	●	●
65		●	●	●	●	●	●	●	●	●	●	●	●	●
70		●	●	●	●	●	●	●	●	●	●	●	●	●
75		●	●	●	●	●	●	●	●	●	●	●	●	●
80		●	●	●	●	●	●	●	●	●	●	●	●	●
90			●	●	●	●	●	●	●	●	●	●	●	●
100			●	●	●	●	●	●	●	●	●	●	●	●
110			●	●	●	●	●	●	●	●	●	●	●	●
120			●	●	●	●	●	●	●	●	●	●	●	●
130			●	●	●	●	●	●	●	●	●	●	●	●
140			●	●	●	●	●	●	●	●	●	●	●	●
150			●	●	●	●	●	●	●	●	●	●	●	●
160				●	●	●	●	●	●	●	●	●	●	●
170				●	●	●	●	●	●	●	●	●	●	●
180				●	●	●	●	●	●	●	●	●	●	●
200				●	●	●	●	●	●	●	●	●	●	●
Box/Piece	1000 ≥25 500	500 ≥45 200 ≥70 100	500 ≥14 200 ≥45 100	200 ≥25 100 ≥85 50	100 ≥50 50	100 ≥50 50	25	25	25	25	25 ≥100 10	10 ≥200 5	10	10